

p-chart for variable sample size

Method - I

Variable control limit :-

On this case we calculate 3 σ limit for each sample separately by using the formula -

$$UCL = \bar{p} + 3 \sqrt{\frac{\bar{p}(1-\bar{p})}{n_i}}$$

$$CL = \bar{p}$$

$$LCL = \bar{p} - 3 \sqrt{\frac{\bar{p}(1-\bar{p})}{n_i}}$$

where $\bar{p} = \frac{\sum d_i}{\sum n_i}$

	<u>Sample size</u>	<u>no of defectives</u>	<u>\bar{p}_i</u>	<u>$\frac{\bar{p}(1-\bar{p})}{n_i}$</u>
1 st	10	3	$\frac{3}{10} = 0.3$	$\frac{0.18 \times 0.82}{10} = 0.01476$
2 nd	15	3	$\frac{3}{15} = 0.2$	0.00984
3 rd	20	4	$\frac{4}{20} = 0.2$	0.00738
4 th	25	5	$\frac{5}{25} = 0.2$	0.005904
5 th	30	3	$\frac{3}{30} = 0.1$	0.00492

$$\bar{p} = \frac{\sum d_i}{\sum n_i}$$

$$= \frac{18}{100}$$

$$= 0.18$$

$$(1-\bar{p}) = 0.82$$

LCL

$$0.18 - 3\sqrt{0.01476}$$

0

0

0

0

0

UCL

$$3 + 3\sqrt{0.01476} = 0.544$$

0.430

0.437

0.411

0.390

Method - II (Standardisation method)

We standardised the statistic p_i by the formula


$$Z_i = \frac{p_i - E(p_i)}{S.E.(p_i)}$$

$$= \frac{p_i - \bar{p}}{\sqrt{\frac{p(1-p)}{n_i}}}$$

$$\bar{p} = \frac{\sum d_i}{\sum n_i}$$

and plot the Z values against the corresponding sample no.

Since n is large $Z_i \sim N(0,1)$ and hence $UCL = +3$ and $LCL = -3$.



c-chart

In many manufacturing or inspection situations, the sample size n - i.e., the area of opportunity is very large (since the opportunities for defect to occur are numerous) and this probability p of the occurrence of a defect is very small such that one spot is very small such that np is finite. In such situation from statistical control we know that the

pattern of variations in data can be represented by poisson distribution and consequently 3 σ control limits based on poisson distribution are used. Since for a poisson distribution mean and variance are equal, if we assume that c is poisson variate with parameter λ we get

$$E(c) = \lambda \text{ and } v(c) = \lambda \text{ Thus } 3\sigma$$

control limits for c -chart are given by

$$UCL = E(c) + 3\sqrt{v(c)} = \lambda + 3\sqrt{\lambda}$$

$$CL = E(c) = \lambda$$

$$LCL = E(c) - 3\sqrt{v(c)} = \lambda - 3\sqrt{\lambda}$$

Case - I (standard specified)

If λ' is the specified value of λ

then $UCL = \lambda' + 3\sqrt{\lambda'}$

$$CL = \lambda'$$

$$LCL = \lambda' - 3\sqrt{\lambda'}$$

Case - II (standards not specified)

if the value of λ is not known, it is estimated by the mean no. of defects per unit. Thus if c_i is the no. of defects observed on the i th ($i=1, 2, \dots, n$) inspected unit then on

estimate of λ is given by

$$\hat{\lambda} = \frac{\sum C_i}{k} = \bar{c}$$

It can be easily seen that \bar{c} is an unbiased estimator of λ . The control limits in this case are given by

$$UCL = \bar{c} + 3\sqrt{\bar{c}}$$

$$CL = \bar{c}$$

$$LCL = \bar{c} - 3\sqrt{\bar{c}}$$

Since c cannot be negative, if LCL given by above formula comes out to be negative it is regarded to be zero.

The central line is drawn at \bar{c} and UCL and LCL are drawn at the values given by

$$UCL = \bar{c} + 3\sqrt{\bar{c}}$$

$$LCL = \bar{c} - 3\sqrt{\bar{c}}$$

The observed no. of defects on the inspected units are then plotted on the control chart. If all the points fall inside the control limits we can say that the process is in control, otherwise if at least one point is outside the control limit we can say

that the process is out of control.

$$\hat{\mu} = \frac{\sum \bar{x}_i}{n} = \bar{\bar{x}}$$

The control limits for the process are given by
 UCL = $\bar{\bar{x}} + 3\sigma/\sqrt{n}$
 LCL = $\bar{\bar{x}} - 3\sigma/\sqrt{n}$

$$UCL = \bar{\bar{x}} + 3\sigma/\sqrt{n}$$

$$LCL = \bar{\bar{x}} - 3\sigma/\sqrt{n}$$

$$UCL = \bar{\bar{x}} + 3\sigma/\sqrt{n}$$

Since a control chart is used to monitor the process, it is important to know the control limits. The control limits are given by above formulas. If the process is out of control, the control limits are given by above formulas. If the process is out of control, the control limits are given by above formulas.

The control chart is given by above formulas. The control chart is given by above formulas. The control chart is given by above formulas.

$$UCL = \bar{\bar{x}} + 3\sigma/\sqrt{n}$$

$$LCL = \bar{\bar{x}} - 3\sigma/\sqrt{n}$$

The observed mean of the inspected units are plotted on the control chart. If all the points fall within the control limits, the process is in control. If any point falls outside the control limits, the process is out of control.